

Notice



☐ CORRECTION
☐ SERVICE FLASH

☒ PRODUCTION CHANGE
☐ ADD INFORMATION

FILE NO.

REVISION 0

Please add this notice to the Service Manual listed below.

Category: **COLOR TELEVISION**

Date: **OCTOBER / 18 / 2012**

Model: **DP42841**

Effective from : Chassis No. **P42841-06**

Destination: **U.S.A. / CANADA**

REF : **No. SM780205-06**

NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. **If the Service Manual Chassis No. does not match the unit's**, additional Service Literature is required. This chassis is similar to Chassis No. P42841-05. Only the **difference** Service Information is given in this manual. For detailed Service Information, refer to the **Original** Service Manual and **Notices** for Chassis No. P42841-05 used in Model DP42841-Z5VT (SM780205).

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

1. IN THE SERVICE ADJUSTMENTS

PAGE 4 ON-SCREEN SERVICE MENU

Item No. **088 OP2 Data** should be changed from **31h** to **32h** in the table and in Note 2.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The reason for change.

A : Misprint B : Quality Reliability C : Standardization
D : Design E : Add as a possible sub F : Schematic location change
G : Purchasing Request

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchangeability	Reason
Page 20, Chassis Electrical Parts List	▲A100	Old	1LG0B10Y11000	ASSY,PWB,ANALOG-COMP-Z5VT	1	NO	D
		New	1LG0B10Y110B0	ASSY,PWB,ANALOG-COMP-Z5VV	1	NO	
	▲A200	Old	1LG0B10Y11100	ASSY,PWB ,MAIN DIGITAL-Z5VT	1	NO	D
		New	1LG0B10Y111B0	ASSY,PWB ,MAIN DIGITAL-Z5VV	1	NO	
	▲EL901	Old	1AV4T40C33400	LCD(V420H2-L06)	1	NO	D
		New	1AV4T40C33700	LCD(T420HVN02.0)	1	NO	
	▲UL901	Old	N0AB4FJ00002	UNIT,POWER-Z5VT	1	NO	D
		New	N0AB4FJ00003	UNIT,POWER-Z5VV	1	NO	
	▲WK72 00-P	Old	K9ZZ00002521	FLEXIBLE FLAT CABLE	1	NO	D
		New	K9ZZ00002522	FLEXIBLE FLAT CABLE	1	NO	

For parts or service contact:

Sanyo Manufacturing Corporation
P.O. Box 2000
3333 Sanyo Road
Forrest City, Arkansas 72335-2000